

# Hot Key Chart in Unigraphics

Hot Key	Function
Ctrl-A	
Ctrl-B	Edit Blank
Ctrl-C	Copy
Ctrl-D	Delete
Ctrl-E	Tools, Expression
Ctrl-F	Fit View
Ctrl-G	Grip Execute
Ctrl-H	
Ctrl-I	Information Object
Ctrl-J	Edit Object display
Ctrl-K	
Ctrl-L	Format Layer Setting
Ctrl-M	Application Modeling
Ctrl-N	File New
Ctrl-O	File Open
Ctrl-P	File Plot
Ctrl-Q	
Ctrl-R	View Operation rotate ( full menu)
Ctrl-S	File Save
Ctrl-T	Edit Transform
Ctrl-U	Execuet User Function
Ctrl-V	Paste
Ctrl-W	Application Gateway

**Ctrl-X**                      **Cut**

**Ctrl-Y**

**Ctrl-Z**                      **Edit Undo**

**Alt-Tab**                      **Toggles Application**

**Alt-F4**                      **Close Active Window**

**Ctrl-Alt-B**                      **Tools, Boundary**

**Ctrl-Alt-C**                      **Tools, CLSF**

**Ctrl-Alt-M**                      **Application Manufacturing**

**Ctrl-Alt-N**                      **Tools, Unisism**

**Ctrl-Alt-W**                      **Application Assemblies**

**Ctrl-Alt-X**                      **Tolls, Lathe Cross-section**

Hot Key	Function
Ctrl-Shift-A	File Save As
Ctrl-Shift-B	Edit Blank, Reserve Blank All
Ctrl-Shift-C	View Curvature Graph
Ctrl-Shift-D	Drafting
Ctrl-Shift-E	
Ctrl-Shift-F	Format Layout , Fit all views
Ctrl-Shift-G	Debug Grip
Ctrl-Shift-H	Hight Quality image
Ctrl-Shift-I	
Ctrl-Shift-J	Preferences, Object
Ctrl-Shift-K	Edit Blank, Unblank Selected
Ctrl-Shift-L	
Ctrl-Shift-M	
Ctrl-Shift-N	Format, Layout New
Ctrl-Shift-O	Format, Layout Open
Ctrl-Shift-P	Tool, Macro Playback
Ctrl-Shift-Q	Quick shaded image
Ctrl-Shift-R	Tool, Macro Record
Ctrl-Shift-S	Tool, Macro Step
Ctrl-Shift-T	Preferences, Selection
Ctrl-Shift-U	Edit Blank, Unblank All of Parts
Ctrl-Shift-V	Format , Visible in View
Ctrl-Shift-W	

**Ctrl-Shift-X**

**Ctrl-Shift-Y**

**Ctrl-Shift-Z**

**View Operation, zoom ( full menu)**

**F1**

**Help On Context**

**F3**

**View Current Dialog**

**F4**

**Information Window**

**F5**

**Refresh**

**F6**

**Quick zoom**

**F7**

**Quick Rotate**